

~ FABRICATION ~



METALWORK

OPERATING INSTRUCTIONS



METALWORK

INTRODUCING

the



MIG WELDER



Mig Welder Machine – Murex and Pulse

Access Level 2 – (see Metal Workshop Induction Guide on Access Levels)

Hand held arc-welding tool that allows you to weld mild steel sections together

PPE Basic

- Suitable cotton-only work coat (provided)
- Leather gloves, rated to EN12477 & 407 (provided)
- Arc-Welding Grade Helmet, rated to BS/EN379 (provided)
- Additional Spectacles or Goggles, rated to BS/EN166 (provided)
- Stout footwear

What to do before use

- ENSURE you have received an INDUCTION into the area BEFORE working
- Persons who have PACEMAKERS or who are PREGNANT should not do this process or use this equipment
- INFORM a member of staff that you are PLANNING to use this piece of equipment
- IF STUDENT, report any faults to any member of workshop technical staff
- IF STAFF, E-mail technical team to report if machine requires maintenance or servicing and whether the machine needs to be taken out of operation and for how long
- VISUAL check of the machine for signs of damage to machine
- ENSURE that there are no flammable, inflammable or combustible materials in the area BEFORE starting your work – if UNSURE, seek advice from any member of the technical team
- PREPARE the metal surfaces you are welding by using a grinding disk or abrading flap wheel

- **ENSURE** all surfaces to be welded are **CLEAN** and **BRIGHT** and there is **NO RUST** on the **SURFACE** of the material that will be **DIRECTLY** welded
- **ENSURE** the welding area is **CLEAN** and free from **OBSTRUCTIONS** preventing you from getting out of the area in the **EVENT OF A FIRE**

How to Use This MIG Welding Equipment

- Refer to any **OPERATING INSTRUCTIONS** given during training or timetabled workshops
- **ENSURE ALL** skin is covered, hair is tied back, ferrous jewellery is removed, **NO** flammable liquids such as lighters is stored on your person
- **SHUT** the welding-grade curtains to the area, isolating the welding light from **OTHERS** sharing the space
- **SECURELY** attach the **EARTH CLIP**, sometimes called a **RETURN LINE**, to the metal bench
- If you are **NOT** working on the bench, **SECURELY** attach the earth clip to your work **DIRECTLY**
- **CLAMP** your work **DOWN** to the bench if required
- Turn **ON** the Argoshield or Argoshield Light cylinder regulator valve. Open the valve **ALL THE WAY** until it stops, then rewind the valve control back **ONE-HALF-TURN**

If you are using the 'Murex' welder follow **OPTION 1**

If you are using the 'Pulse' welder follow **OPTION 2**

Option 1

- **ENSURE** the unit is securely plugged into the **IP-44** (round), three pin socket
- **CUT OFF** old welding wire up to 15mm from the welding **TORCH TIP** - do this **AWAY** from the welding bench or immediate welding area
- Turn **ON** at the switch on the **FRONT** of the welding machine but keep your finger **WELL AWAY** from the trigger section. Hold the torch like a **GUN** - keeping your finger on the body **ABOVE** the trigger **BEFORE** attempting to weld
- Turn **ON** at the machine switch isolator
- Use the dial **BELOW** the **ON** switch to set the required power
- **ADJUST** these **POWER LEVELS**, depending on the thickness of material you are welding; the **THICKER** the gauge of material, the **MORE** power will be required to successfully perform a good weld
- **CHECK** the 'feed speed' using the appropriate dial - this is the rate at which **WELDING WIRE** is fed into the welding pool

- **CLOSE** your welding helmet down, **ENSURING** the auto-dimming setting is **ACTIVE** and set to an appropriate setting; 9-11 or 12 for MIG welding, 13 for ALL arc-welding involving **STICK** welding (known as MMA welding)
- Taking hold of the welding gun in the manner instructed by the technical staff, press the **RED** trigger to begin welding

Option 2

- **ENSURE** the unit is securely plugged into the IP-44 (round), three pin socket
- **CUT OFF** old welding wire up to 15mm from the welding **TORCH TIP**
- Turn **ON** at the switch on the **BACK** of the welding machine but keep your finger **WELL AWAY** from the trigger section. Hold the torch like a **GUN** - keeping your finger on the body **ABOVE** the trigger **BEFORE** attempting to weld
- Using the dial labelled **AMP**, set the required power
- **ADJUST** these **POWER LEVELS**, depending on the thickness of material you are welding; the **THICKER** the gauge of material, the **MORE** power will be required to successfully perform a good weld
- **CHECK** the 'feed speed' using the appropriate dial - this is the rate at which **WELDING WIRE** is fed into the welding pool
- **CLOSE** your welding helmet down, **ENSURING** the auto-dimming setting is **ACTIVE** and set to an appropriate setting; 9-11 or 12 for MIG welding, 13 for ALL arc-welding involving **STICK** welding (known as MMA welding)
- Taking hold of the welding gun in the manner instructed by the technical staff, press the **RED** trigger to begin welding

For BOTH Machines

- Use a **TEST** section to practice and **CHECK** your settings, **ADJUST** power and feed speed as necessary. This will **ALSO** identify any problems with the machine which will need reporting
- When finished, turn **OFF** the machine at the machine
- Turn **OFF** the machine at the wall isolator
- Turn **OFF** the Argoshield gas bottle by turning the valve back until in the **FULLY CLOSED** position
- Turn **OFF** the extraction
- If you have welded **ONTO** the bench grind away excess **BEFORE** leaving the area
- **CLEAR** away any work/debris

Date

I verify that I have read and understood the information detailed within this document

Name

Signature